

September 1, 2017

Dear Valued Customer,

We are issuing this letter to inform you that Welch Allyn will end manufacturing of the Spot Vital Signs® LXi Device on November 30, 2017 globally. As a reminder, on March 31, 2017 Welch Allyn ended manufacturing of the Spot Vital Signs LXi Braun models as well as the Radio accessory.

The below tables outline the parts affected and their associated End of Manufacture date:

End of Manufacture: November 30, 2017									
45MT0-F1	45MT0-F2	45MT0-SW2	45NT0-E6	450T0-E2	450T0-F1	450T0-EX			
45MT0-DN2	45MT0-FN2	45NT0-DN2	45NT0-S1	450T0-DN2	450T0-F2	45MT0-EX			
45MT0-DT2	45MT0-G2	450T0-G2	45NT0-F1	450T0-DT2	450T0-FN2	45NTO-EX			
45MT0-E1	45MT0-I2	45NT0-DT2	45NT0-F2	450T0-E1	450T0-I2	450T0-E6-EC2			
45MT0-E1G	45MT0-L	45NT0-E1	45NT0-FN2	450T0-E1G	450T0-N2	45NT0-E6-EC2			
45MT0-E1T	45MT0-N2	45NT0-E1G	45NT0-G2	45NT0-P2	450T0-P2	45NT0-E1R			
45MT0-E2	45MT0-P2	45NT0-E1T	45NT0-I2	45NT0-S2	450T0-S1	450T0-E1R			
45MT0-E4	45MT0-S1	45NT0-E2	45NT0-L	45NT0-SW2	450T0-S2	45MT0-E1R			
45MT0-E6	45MT0-S2	45NT0-E4	45NT0-N2	450T0-E4	450T0-SW2	45MT0-E6-EC2			
				450T0-E6	45NT0-E1-RNTL	45MT0-E1-RNTL			

End of Manufacture: March 31, 2017									
45ME0-S1	45NE0-E2	45NE0-N2	450E0-N2	450E0-S1	45ME0-E6	45ME0-P2			
45ME0-S2	45NE0-E4	45NE0-P2	450E0-E4	450E0-S2	45ME0-E6-L	45NE0-E2-L			
45ME0-SW2	45NE0-E6	45NE0-S1	450E0-E6	450E0-SW2	45ME0-EC2	450E0-E2-L			
45MEO-E2-L	45NE0-E6-L	45NE0-S2	450E0-EC2	45ME0-E4	45ME0-F1	45ME0-E2-L			
45NE0-EC2	45NE0-F1	45NE0-SW2	450E0-F1	45ME0-DN2	45ME0-F2	45NEO-EX			
45NE0-DN2	45NE0-F2	450E0-DN2	450E0-F2	45ME0-DT2	45ME0-FN2	45ME0-EX			
45NE0-DT2	45NE0-FN2	450E0-DT2	450E0-FN2	45ME0-E1	45ME0-G2	450E0-EX			
45NE0-E1	45NE0-G2	450E0-E1	450E0-G2	45ME0-E1G	45ME0-I2	45ME0-E1R			
45NE0-E1G	45NE0-I2	450E0-E1G	450E0-I2	45ME0-E1T	45ME0-L	45NE0-E1R			
45NE0-E1T	45NE0-L	450E0-E2	450E0-P2	45ME0-E2	45ME0-N2	450E0-E1R			
		4500-922	4500-920	45ME0-E6-EC2	450E0-E6-EC2	45NE0-E6-EC2			



Service and support for these products will continue for up to five years from the end of manufacture date or until parts and accessories are no longer available.

Welch Allyn recommends the Connex® Spot Monitor as a replacement vital signs device for your Spot Vital Signs LXi, as it provides industry leading vital signs monitoring and electronic documentation. Please contact your local Welch Allyn sales representative or customer care for additional details.

We appreciate your understanding in this matter and will continue to help you provide the best possible patient care. Please contact our customer service department at 1-800-535-6663 or your Welch Allyn representative with questions regarding this notice.

Sincerely,

Tiffany Moon

Global Category Manager, Vital Signs

Welch Allyn, Inc.